


RELIANCE®

Bulletin No. REL-JD1.32-4 Group No. 1.32

June 1, 2005 Page 1 of 1

John Deere® 6-404D Vibration Damper.

Reliance Parts Corporation is pleased to announce the addition of vibration damper part number NAR-58172. Shown below are the machine and engine applications for this new vibration damper:

MACHINE MODEL	ENGINE MODEL & SERIAL NO.
4000 Farm Tractor	6-404D S/N 215,000-335,845
4010 Farm Tractor	6-404D S/N →82,801
4020 Farm Tractor	
Machine S/N →200,999	6-404D S/N 82,801-214,999
Machine S/N 201,000→	6-404D S/N 215,000-335,845

It is strongly recommended that these vibration dampers be replaced every 3,000 hours and during engine overhaul. Failure to replace worn or damaged vibration dampers may result in crankshaft breakage and related damage.

Be sure to add this popular vibration damper to your next order.